

## RELEASE NOTE - OMNIPCX OFFICE MAINTENANCE VERSION SYSTEM 910 / 044.001

---

This document describes the corrections delivered with the last maintenance version of OmniPCX Office R9.1.

---

### Revision History

|                             |                               |
|-----------------------------|-------------------------------|
| Edition 1: November 5, 2013 | version 044.001               |
| Edition 2: November 6, 2013 | update: correction in 044.001 |

### **Legal notice:**

Alcatel, Lucent, Alcatel-Lucent and the Alcatel-Lucent logo are trademarks of Alcatel-Lucent.  
All other trademarks are the property of their respective owners.  
The information presented is subject to change without notice.  
Alcatel-Lucent assumes no responsibility for inaccuracies contained herein.  
Copyright © 2013 Alcatel-Lucent. All rights reserved.

## Table of contents

|                                     |   |
|-------------------------------------|---|
| 1 Introduction.....                 | 3 |
| 2 Software references .....         | 3 |
| 2.1 Delivery content.....           | 3 |
| 2.2 Corrections in 044.001 .....    | 4 |
| 3 Historic.....                     | 4 |
| 3.1 Corrections in 041.001 .....    | 4 |
| 3.2 Corrections in 042.001 .....    | 5 |
| 3.3 Corrections in 043.001 .....    | 5 |
| 3.4 Corrections in OMC 20.1a .....  | 6 |
| 3.5 Corrections in OMC 21.1a .....  | 6 |
| 3.6 Corrections in OMC 22.1a .....  | 6 |
| 3.7 Corrections in OMC 23.1a .....  | 7 |
| 3.8 Corrections in OMC 24.1a .....  | 7 |
| 3.9 Corrections in OMC 25.1a .....  | 7 |
| 3.10 Corrections in OMC 26.1a ..... | 7 |

## 1 Introduction

The software version R910 / 044.001 is a maintenance version for the OmniPCX Office RCE - R9.1.

This version does not include new features compared to the version 910/035.001 ; this maintenance version provides only bug corrections.

## 2 Software references

### 2.1 Delivery content

| Item                        | Reference          |
|-----------------------------|--------------------|
| System                      | ALZAA910 / 044.001 |
| OMC Expert                  | OMC 910 / 26.1a    |
| PowerCPU boot-loader (bios) | 000.019            |
| IBS                         | ibs100/003.016     |
| IBS NG                      | ibs_ng100/048.007  |
| IBS PWT (US market)         | ibspwt200/001.024  |
| Multi-UA                    | mlt_ua100/001.006  |
| IP Touch x8 / x8 EE         | 04.33.11           |
| x9 Series (4039 / 4029)     | 03.81.70           |
| x9 Series (4019)            | 03.81.00           |
| 8082 My IC Phone            | 01.012.3           |
| 8002/8012 DeskPhone         | 02.35.03           |
| 4080 IP-DECT AP             | 4910b611           |
| MIPT 300/600                | 109.025            |
| MIPT 310/610                | 120.028            |
| OT 8118 / 8128              | 02.001.008         |
| PIMphony                    | v6.7 Build 2950    |
| ACD application             | 910-9.55.01        |
| OLD application             | 2.3.9              |



#### Warning

The version 044.001 contains new uboot-loader version 000.019 for the PowerCPU :

- The new Boot-loader will be loaded when the system restarts in 044.001 (first cold start after swap),
- DO NOT SWITCH OFF THE SYSTEM DURING THE BIOS UPGRADE (stopping the bios flashing will put the PowerCPU in permanent fault state and the board has to be sent to the repair centre).

**Reminder :** on the Compact Edition cabinet, the uboot-loader is not automatically selected for this type of cabinet. When loading the version 044.001, it is necessary to select manually the Boot-loader in the list of items to be sent to the system.

## 2.2 Corrections in 044.001

| Identifier   | Siebel      | Headline                                                                                      |
|--------------|-------------|-----------------------------------------------------------------------------------------------|
| crms00458606 | 1-152580241 | Not possible to configure Fax destination to DDI                                              |
| crms00429512 |             | DSP channel de-allocation is not proper and IP-DECT sends "486 Busy here"                     |
| crms00432637 | 1-147272151 | SIP OBS: ext call to an IP-DECT subscriber via the Auto Attendant is not possible             |
| crms00440942 | 1-148311211 | Metering issue for attendant set                                                              |
| crms00444646 |             | No voice path between OT4135 and a set after My IC Mobile in SIP mode transfers the call      |
| crms00446416 | 1-150156761 | SIP OBS-BIV #94: Blocking of the My IC Mobile Android application                             |
| crms00455186 | 1-152058681 | SIP OBS-BIV #96: after completing ExtCallTransf, PIMphony IP keeps sending RTP stream forever |
| crms00456786 | 1-152013061 | Problem with taxation tickets                                                                 |
| crms00458606 | 1-152580241 | Not possible to configure Fax destination to DDI                                              |

## 3 Historic

List of main corrections between the software version 910/035.001 – 910/044.001 and OMC 910/19.2a – 910/26.1a.

### 3.1 Corrections in 041.001

| Identifier   | Siebel      | Headline                                                                                                                     |
|--------------|-------------|------------------------------------------------------------------------------------------------------------------------------|
| crms00440408 | 1-148289191 | ACK with SDP                                                                                                                 |
| crms00372793 | 1-133807461 | SIP Telenor: basic outcall released after a few minutes (OXO ignores new value of RFC4028 timer)                             |
| crms00428734 | 1-146173195 | CSTA changes from R8.0 to R8.2                                                                                               |
| crms00439293 |             | Incomplete display of main license key in the NOE set under operator option                                                  |
| crms00441407 |             | Voice mail count is not properly updated in 8002/8012 set                                                                    |
| crms00442248 |             | Nomadic SIP Trunk: Call release issue (Delay/unwanted release tone)                                                          |
| crms00443396 | 1-149400202 | Feature Own Voice Mail is not working with IP DECT                                                                           |
| crms00443914 |             | My IC Mobile iPhone SIP: random release                                                                                      |
| crms00444407 |             | 8002/8012 : Wrong "P-Calling-Info" during transfer in ringing                                                                |
| crms00445217 | 1-149801621 | No http protocol traced with the WebDiag TCPDUMP tool                                                                        |
| crms00445227 | 1-149801640 | Incomplete TCPDump traces of HHTP protocol via WebDiag                                                                       |
| crms00445362 |             | SIP : Call failure when early-media is received after INVITE without SDP to SIP trunk                                        |
| crms00445644 |             | No voice path when internal transfer made between My IC Mobile nomadic via SIP and secondary VT set nomadic diverted via SIP |
| crms00445804 | 1-150019751 | SIP OBS-BIV #93: No local ring back tone upon reception of SIP/ 180 SDP but NO P-Early-Media                                 |

|              |  |                                                                                      |
|--------------|--|--------------------------------------------------------------------------------------|
| crms00446414 |  | No participant Id in GetTelephonicState web service response                         |
| crms00446797 |  | My IC Mobile# Hold and Retrieve fails after the second attempt for SIP phones        |
| crms00448475 |  | Display issue in My IC Mobile Android when incoming call is answered in locked state |

## 3.2 Corrections in 042.001

| Identifier   | Siebel      | Headline                                                                                         |
|--------------|-------------|--------------------------------------------------------------------------------------------------|
| crms00355936 | 1-130049801 | System reset with "Suicide DBM" info (occurs randomly in context of ACD with high traffic)       |
| crms00412352 | 1-142714391 | OXO and VLAN settings: voice default GW is wrong                                                 |
| crms00415148 | 1-143614161 | SCR routing table wrong message translation (German)                                             |
| crms00425019 | 1-145583691 | Incoming BIV calls with CLIR are sent to OP group                                                |
| crms00427001 | 1-145418951 | 8012 keeps ringing                                                                               |
| crms00428755 | 1-145998001 | VLAN for voice and data does not work                                                            |
| crms00429868 |             | On recording second time in a set, the call is released with XLite                               |
| crms00430743 | 1-145733323 | Barring management issue with My IC Mobile                                                       |
| crms00433312 | 1-147357781 | 8002/8012 diversion                                                                              |
| crms00434299 | 1-147602850 | 8002/8012 phone strings translation in Lithuanian language                                       |
| crms00438236 | 1-148428363 | System reset after transfer tests on Helios IP 2n                                                |
| crms00440962 | 1-142017221 | SIP phone : conference fails after swap between call legs                                        |
| crms00441022 | 1-149016791 | Non working of SG3 to SG3 fax T38 transmission on SFR infra                                      |
| crms00442625 | 1-149392763 | ACD Statistic export windows word 'Close' on button is shortened in German                       |
| crms00445634 | 1-149925271 | SIP OBS-BIV #92: basic calls from IP set 8002/8012 to PSTN are KO (RTP emitted has 30ms framing) |
| crms00447895 |             | Communication released when My IC Mobile in nomadic SIP trunk puts its correspondent on hold     |
| crms00448993 |             | 8002/8012 - Wrong "P-Calling-Info" during supervised Queued event                                |
| crms00449053 | 1-150104335 | E-Mail notification translation into Czech language wrong                                        |
| crms00449096 | 1-149988671 | Click noise when the greeting is recorded from IP phone set                                      |
| crms00450003 | 1-150597755 | Issue outgoing call to emergency number (000)                                                    |

**New 8002/8012 DeskPhone version 02.35.1**

## 3.3 Corrections in 043.001

| Identifier   | Siebel      | Headline                                                                  |
|--------------|-------------|---------------------------------------------------------------------------|
| crms00434156 |             | Dual mode : no voice prompt for Meet me conference activation             |
| crms00438007 | 1-148378111 | Issue with DISA Transit between ISDN and SIP Public trunk                 |
| crms00440053 | 1-147950141 | DAP - top LED (yellow) stay in fast blink                                 |
| crms00440561 | 1-148913951 | DECT registered many times in DAP                                         |
| crms00441050 | 1-148738341 | CLIP presentation for attendant call and dynamic routing to OXO 2 via SIP |

|              |             |                                                                                                                                 |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------|
| crms00441916 | 1-149196713 | IP-DECT not coming up after system reset                                                                                        |
| crms00445646 |             | When the MLAA chained free dialing reaches the My IC Mobile as the second call, then there is no voice path                     |
| crms00446069 | 1-147143361 | MLAA - Timer before playing message for error during a transfer is not working                                                  |
| crms00447533 | 1-150407904 | 8012 phone strings translation in Latvian language                                                                              |
| crms00448937 |             | One way voice path is present & OXO goes for reset randomly after a transfer on ringing over the SIP trunk involving SIP Phones |
| crms00454785 |             | After a SIP phone has answered to a call with preannouncement during distribution, it cannot put the call on hold               |
| crms00457247 | 1-152545171 | AU request for default value modification                                                                                       |
| crms00451459 | 1-151183931 | Daylight saving time (DST) not working on some OXOs                                                                             |

**New 8002/8012 DeskPhone version 02.35.3**

**New IP NOE (x8 & x8 EE) version 04.33.11**

**New NOE TDM (x9) version 4019 : 3.81.00 – 4029/39 : 3.81.70**

**New IP DECT DAP version : 4910b53d.dwl**

**New ACD/MLAA engine : 910.040**

### 3.4 Corrections in OMC 20.1a

| Identifier   | Siebel      | Headline                   |
|--------------|-------------|----------------------------|
| crms00364531 |             | New OS Support - Windows 8 |
| crms00392309 | 1-138071701 | OMC900/5.1a and win7-64    |
| crms00442379 | 1-149240231 | OMC error while installing |

### 3.5 Corections in OMC 21.1a

| Identifier   | Siebel      | Headline                                 |
|--------------|-------------|------------------------------------------|
| crms00444855 | 1-149818961 | OMC 910 / 20.1a fail to start            |
| crms00445647 | 1-149973648 | Unable to add IP extensions with OMC 910 |

### 3.6 Corrections in OMC 22.1a

| Identifier   | Siebel      | Headline                                                                            |
|--------------|-------------|-------------------------------------------------------------------------------------|
| crms00344538 | 1-127216781 | OMC Software Download Data Saving option is not set                                 |
| crms00418936 | 1-144396821 | Manager / Assistant feature wrong behavior with T-Systems default subscriber config |
| crms00438896 |             | Subnet mask option not allowed in OMC when first byte is 255                        |
| crms00440496 |             | OMC Display is not proper when existing entry is modified as "Any Device"           |
| crms00441675 |             | DHCP Option 28 broadcast-address option not allowed in OMC when first byte is 255   |
| crms00442510 | 1-149364001 | Manager/Secretary configuration issue                                               |
| crms00443531 | 1-149400118 | OMC DHCP configuration ergonomics                                                   |

### 3.7 Corrections in OMC 23.1a

| Identifier   | Siebel      | Headline                                         |
|--------------|-------------|--------------------------------------------------|
| crms00442628 | 1-149399886 | MLAA typo error in German                        |
| crms00442633 | 1-149400011 | MLAA line parameter wrong display of ACD entries |
| crms00445386 | 1-149918638 | ACD displays only * (stars) in SCR tab           |

### 3.8 Corrections in OMC 24.1a

| Identifier   | Siebel      | Headline                                                                                        |
|--------------|-------------|-------------------------------------------------------------------------------------------------|
| crms00429884 | 1-146340631 | Cannot access ACD SCR Services & Global Central Services                                        |
| crms00440332 |             | Classless static routes not working                                                             |
| crms00451374 | 1-151213441 | SIP: config of password in OMC/ARS/GW-Parms does not permit to type some special chars like "?" |
| crms00451580 | 1-150617958 | OXO file not showing correct VOIP subscriber                                                    |
| crms00452325 | 1-151251831 | Error opening Central Services Global Info                                                      |
| crms00453258 | 1-151638568 | ACD typo error (German)                                                                         |
| crms00453294 |             | Row separators invisible in Advanced DHCP configuration window                                  |

### 3.9 Corrections in OMC 25.1a

| Identifier   | Siebel      | Headline                                                                                       |
|--------------|-------------|------------------------------------------------------------------------------------------------|
| crms00393892 | 1-138578381 | Defect # 59 : UAI16 problem when changing numbering plan                                       |
| crms00411229 | 1-142293349 | OMC 900/13.1a - My IC Phone Reset function                                                     |
| crms00453748 | 1-149032981 | OMC -- not possible to see Password length offline                                             |
| crms00454671 | 1-151749423 | Unable to configure the ACD setup with OXO release R510                                        |
| crms00457440 | 1-152246531 | OMC 910/22.1a on Windows 7 does not install visual C++ component automatically                 |
| crms00458036 |             | OMC save in command line stops working on PBX data id failure (seen on RSC server)             |
| crms00458065 |             | OMC slow when opening subscriber Features information if subscriber is secondary of a MultiSet |

### 3.10 Corrections in OMC 26.1a

| Identifier   | Siebel      | Headline                                                                                                     |
|--------------|-------------|--------------------------------------------------------------------------------------------------------------|
| crms00436356 | 1-147385443 | Issue with OMC connection in Windows 7 system                                                                |
| crms00460438 | 1-152740071 | Problem with change of CPU type in off-line database in OMC R910/24.1a running in Windows 7 operating system |

### Follow us on Facebook and Twitter

Stay tuned on our Facebook and Twitter channels where we inform you about:

- New software releases
- New technical communications
- AAPP InterWorking Reports
- Newsletter
- Etc.



[twitter.com/ALUEnterpriseCare](https://twitter.com/ALUEnterpriseCare)



[facebook.com/ALECustomerCare](https://facebook.com/ALECustomerCare)

### Submitting a Service Request

Please connect to our [eService Request](#) application.

Before submitting a Service Request, make sure that:

- In case a Third-Party application is involved, that application has been certified via the AAPP
- You have read through the Release Notes which lists new features available, system requirements, restrictions etc. available in the [Technical Documentation Library](#)
- You have read through the Troubleshooting Guides and Technical Bulletins relative to this subject available in the [Technical Documentation Library](#)
- You have read through the self-service information on commonly asked support questions, known issues and workarounds available in the [Technical Knowledge Center](#)

- END OF DOCUMENT -

---