

OMNIPCX OFFICE R9.0

SYSTEM VERSION 900 / 048.001

This document gives the information of new OmniPCX Office system version 048.001

Revision History

Edition 1: March 18, 2013 creation of the document

Legal notice:

Alcatel, Lucent, Alcatel-Lucent and the Alcatel-Lucent logo are trademarks of Alcatel-Lucent.
All other trademarks are the property of their respective owners.
The information presented is subject to change without notice.
Alcatel-Lucent assumes no responsibility for inaccuracies contained herein.
Copyright © 2013 Alcatel-Lucent. All rights reserved.

Table of contents

1 Introduction.....	3
2 Software level	3
3 Software reference.....	3
4 Main correction delivered	4

1 Introduction

The software version R900 / 048.001 is a maintenance version of the OmniPCX Office RCE – R9.0.

This version will be equipped on the new systems going out of manufacturing from week 14/2013 for Generic Market , Telekom Austria and Telecom Italia.

This version supports the new devices 8002 / 8012 My IC Phone.

2 Software level

Version 900 / 048.001 has the same level of correction than 900 / 041.002.

Fix delivered in version R900 / 042.001 will be reported in a further maintenance version (eg 900 / 05x.00x) available for download on the ALE Portal.

3 Software reference

Item	Reference
System	ALZ900 / 048.001
OMC Expert / Easy / EasyPlus	OMC 900 / 20.1a
Boot-loader (bios)	000.018
IP Touch 4068 / 4038 / 4028	04.32.42
IP Touch 4018	04.32.43
IP Touch x8 EE	04.32.43
x9 Series (4039 / 4029)	03.81.50
x9 Series (4019)	03.80.40
8082 My IC Phone	R260.01.011.0
8002 / 8012 My IC Phone	R100.02.30.00
DECT 500	00.52
8232	41.81
MIPT 300/600	109.025
MIPT 310/610	120.027
OT 8118 / 8128	02.001.008
OT 4135	1.5.13.7
IBS	ibs100/003.016
IBS NG	ibs_ng100/049.003
IBS PWT (US market)	ibspwt200/001.024

4 Main correction delivered

The table hereafter lists the main correction delivered since version 900 / 033.002

▼ Corrections in 037.002

Identifier	Siebel	Headline
crms00387037		In ACD line parameter configuration CLI & DDI max digits should be 20
crms00398665		IP-DECT : during validation of forward, bad tone is present
crms00405326	1-141099504	TS beta : SIP GW crashed after SW upgrade
crms00405473	1-141148986	OXO made reset 03 after upgrade to 900/033.002
crms00406028	1-141155535	OXO system reset when making SIP call with a MP112 SIP device
crms00406527	1-141403041	Manager App is not displayed on My IC Phone QT Target
crms00406535	1-141403851	RTP direct is not working with IP DECT
crms00401096	1-139849341	System default value modification for Austria country target
crms00407955		Bad system answer when a SIP phone activates a system diversion thanks to the diversion prefix
crms00406462		TS betasystem : system reset due to SIP Phone GW crash

▼ Corrections in 040.002

Identifier	Siebel	Headline
crms00376744		Groupware: notification application access in menu
crms00391037		My IC phone 8082 Video - Transferred video call should switch to audio call
crms00394315		MY IC Phone 8082: recorded conversation count is getting added in new Voicemail counter list after a .cdb restore
crms00394803		My IC phone 8082 not in ring back state when blind transferred on ring to busy phone
crms00394849		Answer button is not present for second incoming call when we deflect first call to another set in My IC Office
crms00400990	1-140138903	My IC Phone list in OMC and Webdiag is different
crms00401716		CSTA error on pickup request
crms00404686		In ACD-SCR , call not landing when then number "9" is used as trunk group number or attendant based on the different target
crms00405895	1-141205629	My IC Phone call log not updated correctly
crms00406517	1-141205621	Not answered hunting group call on DECT 8232 and 500 cannot be called back
crms00406643	1-141437091	SCR Client Code not terminated with # is not working
crms00407043		My IC Office linked to SIP phone, displays wrong public number
crms00407467	1-141663431	Calls from My IC Phone to OT4135 fail in G722
crms00407686	1-141711821	8232 DECT time is 1 hour more than real time
crms00407914		BYE request from IP DECT is not challenged with 401 from OXO
crms00408100	1-141804351	Call VM is not working on My IC Phone
crms00408190	1-141803351	Not possible to register several DECT handsets
crms00408221	1-141829398	SIP AT: new FAX-CNG feature does not work as requested
crms00410253	1-142299201	System reset : Albator: process exit abnormally
crms00394290		Unable to pick up the call in IP DECT
crms00408210	1-141829301	SIP AT: new G711-MOH feature does not work in context of outgoing calls

crms00411306	1-142568160	Open RCE Fax sending doesn't work in R900
--------------	-------------	---

▼ Corrections in 040.003

Identifier	Siebel	Headline
crms00411877		IP DECT phone requires an IP User license
crms00413501		IP DECT Fails to register if license is exceeded in OMC - Call Handling correction

▼ Corrections in 041.002

Identifier	Siebel	Headline
crms00411420		Music on hold played with very bad quality
crms00415356	1-143683559	Call lost when SCR routes a call to busy set
crms00415465	1-143717641	OXO sends invalid "SIP registration"
crms00416836	1-143924283	Global/individual greetings behavior
crms00400176		Nomadic diversion gets failed over SIP trunk
crms00416130		OXO-SIP : the hold of a sip trunk from a SIP phone, with codec pass-through activated, fails
crms00416134		OXO resets when SIP Phones puts the remote SIP Trunk call on HOLD

Follow us on Facebook and Twitter

Stay tuned on our Facebook and Twitter channels where we inform you about:

- New software releases
- New technical communications
- AAPP InterWorking Reports
- Newsletter
- Etc.



twitter.com/ALUEnterpriseCare



facebook.com/ALECustomerCare

Submitting a Service Request

Please connect to our eService application at:

<https://businessportal.alcatel-lucent.com/alugesdp/faces/gesdp/customerSupport/CustomerSupport.jspx>

Before submitting a Service Request, make sure that:

- In case a Third-Party application is involved, that application has been certified via the AAPP
- You have read through the Release Notes which lists new features available, system requirements, restrictions etc. available in the [Technical Knowledge Base](#)
- You have read through the Troubleshooting Guides and Technical Bulletins relative to this subject available in the [Technical Knowledge Base](#)

- END OF DOCUMENT -
